





# ASSEMBLY INSTRUCTION

## NP3TT-1 | 0.173" (4.4 mm) BANTAM-TYPE MINIATURE PLUGS


① **Push bushing and cover onto cable**



② **Cable preparation**




③ **Insert the prepared cable into the connector**




④ **Soldering**

Solder the inner leads to the solder cups. Make sure that the central cup is properly covered with solder thus securing the threaded joint between tip and cup.



⑤ **Hex-Crimping**

To connect the ground and for proper cable retention: crimp the rear part of the connector with the NEUTRIK Crimp tool.




⑥ **Move forward bushing and cover as far as easily possible.**



Recommendation: Check electrical connection before final assembly.


⑦ **Final assembly:**

Insert into the tool - press together.



**Assembly tool:**

The HX-TT-1 consists of a crimp tool and a press tool für NP3TT-1-\*



<b>NEUTRIK AG</b>	LI	T: +423 / 237 24 24	F: +423 / 232 53 93	<b>NEUTRIK Vertriebs GmbH</b>	DE/NL/AT	T: +49 8131 / 280 890	F: +49 8131 / 280 830
<b>NEUTRIK Zürich AG</b>	CH	T: +41 44 / 736 5010	F: +41 44 / 736 5011	<b>NEUTRIK France</b>	FR	T: +33 1 / 4131 6750	F: +33 1 / 4131 0511
<b>NEUTRIK USA Inc.</b>	USA	T: +1 732 / 901 9488	F: +1 732 / 901 9608	<b>NEUTRIK Tokyo Ltd.</b>	JP	T: +81 3 / 3663 4733	F: +81 3 / 3663 4796
<b>NEUTRIK (UK) Ltd.</b>	UK	T: +44 1983 / 811 441	F: +44 1983 / 811 439	<b>NEUTRIK Hong Kong Ltd.</b>	HK	T: +852 / 2687 6055	F: +852 / 2687 6052